EPC-S201 User Note

May, 2023

×

The following problems will occur when the Windows

SUSI driver released before 2023/02 is installed on

Windows 10 22H2 (Build number 19045.2xxx)

- 1. The SUSI4 Driver node does not appear on DeviceManager
- 2. Execute SUSIDemo directly, the following error message will appear

Microsoft .NET Framework

Continue, t	he application w	occurred in your application. It will ignore this error and attemp ion will close immediately.	
Unable to I routine faile	oad DLL 'SusiD d. (Exception fr	evice": A dynamic link library (om HRESULT: 0x8007045A)	DLL) initialization
▼ Details		Continue	Quit

Here are two solutions

1. Customers are requested to update to the latest version. The latest version of Windows 10 22H2, version 19045.3031, can be installed normally and there is no problem in use

2. If the customer cannot connect to the Internet to update, please use the link below to work around, the process is as follows

- a. First execute the program SUSIPatch.exe
- b. Install SUSI
- c. Restart the computer