Advantech SE Technical Share Document

Date	2020/2/3		
Category	□ FAQ ■ SOP □ Driver Tech Note	**Related Product**	WebAccess SCADA/Saas Composer
Abstract	如何製作 Table 並同時連結多個測點		
Keyword	WebAccess SCADA/Saas Composer		
Related OS	Win7, Windows Server 2008 / 2012 / 2016, Win10		

Revision History


Date	Version	Author	Reviewer	Description
2020/2/3	V1.0	Simon.Chiu	Nick.Liu	WebAccess 8.4.3

- **Problem Description & Architecture:**
- **Brief Solution - Step by Step:**


1. 請先在畫紙空白處按左鍵，至右邊選擇→擴展→資料綁定




2. 將要連結的測點設定於此



3. 接著到圖標→UI→將 customer1 拖曳出來即為 Table 圖表：



4. 點選拖曳出來的 Table 選擇右手邊基礎→標簽，請自行給予名稱



5. 點選拖曳出來的 Table 選擇右手邊基礎→表格繪製：



6. 請提供表格總共有幾行幾列




7. 若此欄位需要使用文字呈現，請參考下圖操作：



8. 若此欄位需要使用測點數據呈現，請參考下圖操作：



9. 所有行列都設定完了以後請按下確定，將圖表存檔後按下播放鍵來確認數據是否有上傳



- **Pin Definition (in case of serial connection):**

- **Reference:**