Advantech AE Technical Share Document

| Date	2018 / 11 / 28	SR#	1-3609403743
Category	■FAQ □SOP	Related OS	Ubuntu 12.04
Abstract	How to solve the time different between OS & BIOS		
Keyword	Ubuntu 12.04, BIOS		
Related Product	UNO-series		

■ **Problem Description:**

  Ubuntu12.04 would happen the time is different with BIOS even change to the different time zone.

■ **Problem Analysis:**

  Do the cross test with different OS(Windows or newer version Ubuntu)& different version BIOS,
  Confirmed the time issue is relative with Ubuntu12.04 parameter.

■ **Brief Solution - Step by Step:**

  1. To execute the below command for open the /etc/default/rc folder
  sudo gedit /etc/default/rcS
  2. Change the command from UTC=yes to UTC=no in the file and add one command GMT=no as below image.
  3. Save the file & reboot the device. The time will be sync between in BIOS & OS.

■ **Contact Window and File Link:**

  If you have any questions, please contact Jerry.Cheng@advantech.com.tw