

Advantech AE Technical Share Document

Date	2015 / 04 / 07	SR#	
Category	■ FAQ □ SOP	Related OS	Win7/ WinXP
Abstract	How to install USB driver for WOP-2000T		
Keyword	WOP, WebOP		
Related Product	WOP-2000T		

■ Problem Description:

Before user download project to HMI by USB cable, you need to install USB driver on your development Computer. Otherwise WebOP Designer couldn't recognize your device by USB interface.

■ Brief Solution - Step by Step:

How to Install USB Driver for WOP-2000

1. 在"我的電腦"按右鍵選擇內容



2. 裝置管理員



3. 假若沒有安裝過 Driver, 會看到“?”無法識別的裝置 “Neo HMI”




4. 選擇更新驅動程式軟體



5. 瀏覽電腦上的驅動程式軟體



6. 路徑請選擇 WebOP Designer 安裝路徑下的 USB 資料夾 32bit/64bit



7. 下一步



8. 選擇安裝



9. 安裝完成後, 即可用 USB 下載 WebOP 專案至人機.



■ **Reference:**

N/A