

Product:

KW Multiprog; PAC; ADAM -5510KW; ADAM -5550KW; AMAX-2050KW

Abstract:

Utilizing the "Cross Window" for Debugging.

Description:

In my program I have created a lot of variables. However when doing the debugging, it is hard to locate all the interested variables at the same time. Is there a way to generate a table which only shows the variable that I am interested and where I can change the variable number directly?

Solution:

This can be done through the "Watch Window" function.

First run the program and under debug mode on. Click the Watch Window icon. Right click the variable which would like to show and select "Add to Watch Window". It will add this variable into the "Watch Window" list and the value can be changed by double click.

