

Assembly Notice between AIMB- 763 and ACP-2010MB/ACP-2320MB/ACP-4000MB IPC-510MB/IPC-610MB-H/IPC-7143/IPC-7220

Root Cause:

AIMB-763 doesn't provide an external connector for PS/2 port. Front-access PS/2 function of chassis listed above would face a difficulty to enable it.

Solution:

- (1) If customers need a PS/2 port support in front-panel of chassis above with AIMB-763, kindly refer picture below to enable front PS/2 interface of these chassis.
- (2) Please order an extra cable, 1700006917 to install AIMB-763 and PS/2 module of chassis.

Part number	Function
1700006917	To enable the front PS/2 (Keyboard/Mouse) interface on ACP-2010MB/2320MB/4000MB & IPC-510MB/610MB-H/7143/7220

Case III. 1700006917 enables the front PS/2 interface




Fig.3 1700006917 connect with Keyboard/Mouse connector on motherboard and the KB/USB board on front panel