

Advantech Corporation

EKI-5000 Series

Release Note

- **Firmware version: v1.18.0002**

Release Date	2017/11/28
Engineer	Leo.Lin
Final Approval	JasonC.Chiou

I. Release Brief

Firmware Version: v1.18.0002

Purpose of Release: Bug fixed.

Customer: Advantech pOS 3.0

II. Changes

i. New Feature Release

- a. Disable default setting of broadcast storm
- b. Support VIP port enable/disable for EKI Utility
- c. Support reboot action for SNMP MIB
- d. Change EEE factory default value to disabled

ii. Bugs Fix

- a. [EKI-5729P] Fix fiber port initial fail bug.
- b. Fix 47ms power off/PoE port mapping disable issue
- c. Fix default gateway restore after preview function disabled to enabled
- d. Fix PoE LED not work issue (I2C 20ms delay, PoE LED status check).
- e. Fix model name change to default EKI-5728 during booting with interruption of power supply
- f. Fix MAC address change to default and board LED change during booting with interruption of power supply
- g. Fix PoE LED not initialize issue

iii. The known unfixed issues

N/A

iv. MD5 checksum