SE SOP


ARK-3532 FAN Kit SOP

Date: 24 / 02 / 2021


Approved by	Checked by	Prepared by
		Franck




1. Removing the housing



2. Removing the iron plate



3. Install the DC Cable on the blind hole




Cable P/N: 1700031865-01


4. Install the fan on the iron housing

screw P/N: 1930008608

*8



5. screwing



6. Install the FAN Kit back to the machine.

